



	E=2200	E=2200	E=2200	E=2400	E=2400	E=2400
	FRD	FR	PDS	FRD	FR	PDS
A	1672	1667	1667	1672	1667	1667
B	726	726	726	726	726	726
C	1136	1136	1136	1136	1136	1136
D	2596	2603	2823	2795	2802	3022
H	1030	1030	1030	1030	1030	1030
L	2595	2595	2595	2794	2794	2794
PESO	292	298	311	296	302	315
PESO	314	320	333	318	324	337